Maryland Historical Trust

Maryland Inventory of Historic Properties number:	77			
Name: #12030/MD1360Vez	PalaRo	KUNST		
The bridge referenced herein was inventoried by the Maryland Historic Bridge Inventory, and SHA provided the Trust with el The Trust accepted the Historic Bridge Inventory on April 3, 2 determination of eligibility.	State Highway Ac gibility determina	dministration a	ary 20	001.
-				
MARYLAND HISTORIC Eligibility RecommendedX		Recommended	l	
Criteria:ABCD Considerations:A	BCr)EF _	G_	_None
Comments:				
Reviewer, OPS:_Anne E. Bruder	Date:_	_3 April 2001_		
Reviewer, NR Program: Peter E. Kurtze	Date:_	_3 April 2001_		

MHT No. <u>HA-1977</u>

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

SHA Bridge No. 12030 Bridge name MD 136 over Big Branch
LOCATION: Street/Road name and number [facility carried] MD 136 (Harkins Road)
City/town Harkins Vicinity X
County Harford
This bridge projects over: Road Railway Water X Land
Ownership: State X County Municipal Other
HISTORIC STATUS: Is the bridge located within a designated historic district? Yes No _X National Register-listed district National Register-determined-eligible district Locally-designated district Other
Name of district
BRIDGE TYPE: Timber Bridge: Beam Bridge: Truss -Covered Trestle Timber-And-Concrete Stone Arch Bridge: Metal Truss Bridge
Movable Bridge: Swing Bascule Single Leaf Bascule Multiple Leaf Vertical Lift Retractile Pontoon
Metal Girder: Rolled Girder: Rolled Girder Concrete Encased Plate Girder: Plate Girder Concrete Encased
Metal Suspension
Metal Arch
Metal Cantilever
Concrete X: Concrete Arch: Concrete Slab: Concrete Beam X: Rigid Frame Other: Type Name:

DESCRIPTION: Setting: Urban	Small town	Rural	X	
Describe Setting:				
Bridge No. 12030 carries MD 13 runs east-west and Big Branch fl and is surrounded by woods and	lows north-south. The bri	Big Branch in Hidge is located i	Iarford County. MD 136 in the vicinity of Harkins,	
Describe Superstructure and Su	ıbstructure:			
Bridge No. 12030 is a single-spar 1934 and the abutments were r roadway width of 28 feet. The o which support a concrete deck ar a bituminous wearing surface. approaches have steel guard rai there are flared, concrete wing v	repaired in 1994. The stout-to-out width is 32 feet. In concrete parapets. The The structure has piercells. The substructure con	The superstructure is 38 for The superstructure deck is ed, concrete passists of two (2)	eet long and has a clear cture consists of T-beams is 7 inches thick and it has arapets and the roadway concrete abutments and	
According to the 1996 inspection report, this structure was in satisfactory condition. The concrete beams have small rust spots with areas of surface erosion. The abutments have vertical and diagonal cracks and areas of surface erosion at the water line. The wing walls have spalling at the bottom, random cracks and surface erosion at the water line. The concrete parapet has medium to heavy scale with random cracking. Both railings have heavy spalling at the curb and the southern railing has exposed reinforcing bars.				
Discuss Major Alterations:				
According to the inspection representation concrete beam (#6) was patched		ents were repai	red in 1994 and one (1)	
HISTORY:				
WHEN was the bridge built: 19 This date is: Actual X Source of date: Plaque Other (specify): State Highway	Estin	•	iles/inspection form	
WHY was the bridge built?				
The bridge was constructed in reincreased load capacity.	sponse to the need for a n	nore efficient tra	ansportation network and	
WHO was the designer?				
State Roads Commission				
WHO was the builder?				
Unknown	50	8		

N/A

Was this bridge built as part of an organized bridge-building campaign?

There is no evidence that the bridge was built as part of an organized bridge building campaign.

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have Nat	ional Register significa	nce for its	association v	with:
A - Events	B- Person			
C- Engineering/arc	:hitectural character	X		

The bridge is eligible for the National Register of Historic Places under Criterion C, as a significant example of concrete beam construction. In addition, the structure is a good example of the State Roads Commission standard plan of 1933. The structure has a high degree of integrity and retains such character-defining elements of the type as longitudinal beams, slab, pierced parapets, abutments and wing walls.

Was the bridge constructed in response to significant events in Maryland or local history?

The earliest concrete beam bridges in the nation were deck girder spans that featured concrete slabs supported by a series of longitudinal concrete beams. This method of construction was conceptually quite similar to the traditional timber beam bridge which had found such widespread use both in Europe and in America. Developed early in the twentieth century, deck girder spans continued to be widely used in 1920 when noted bridge engineer Milo Ketchum wrote *The Design of Highway Bridges of Steel, Timber and Concrete* (Ketchum 1920).

Although visually similar to deck girder bridges, the T-beam span features a series of reinforced concrete beams that are integrated into the concrete slab, forming a monolithic mass appearing in cross section like a series of upper-case "T"s connected at the top. Thaddeus Hyatt is believed to have been the first to come upon the idea of the T-beam when he was studying reinforced concrete in the 1850s, but the first useful T-beam was developed by the Belgian Francois Hennebique at the turn of the present century (Lay 1992:293). The earliest references to T-beam bridges refer to the type as concrete slab and beam construction, a description that does not distinguish the T-beam design from the concrete deck girder. Henry G. Tyrrell was perhaps the first American bridge engineer to use the now standard term "T-beam" in his treatise *Concrete Bridges and Culverts*, published in 1909. Tyrrell commented that "it is permissible and good practice in designing small concrete beams which are united by slabs, to consider the effect of a portion of the floor slab and to proportion the beams as T-beams" (Tyrrell 1909:186).

By 1920, reinforced concrete, T-beam construction had found broad application in standardized bridge design across the United States. In his text, *The Design of Highway Bridges of Steel, Timber and Concrete*, Milo S. Ketchum included drawings of standard T-beam spans recommended by the U.S. Bureau of Public Roads as well as drawings of T-beam bridges built by state highway departments in Ohio, Michigan, Illinois, and Massachusetts (Ketchum 1920). By the 1930s the T-beam bridge was widely built in Maryland and Virginia.

Maryland's roads and bridge improvement programs mirrored economic cycles. The first road improvement of the State Roads Commission was a 7 year program, starting with the Commission's

establishment in 1908 and ending in 1915. Due to World War I, the period from 1916-1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920-1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund (with an equal sum from the counties) the building of lateral roads. The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had been inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930's. Most improvements to local roads waited until the years after World War I.

In the early years, there was a need to replace the numerous single lane timber bridges. Walter Wilson Crosby, Chief Engineer, stated in 1906, "the general plan has been to replace these [wood bridges] with pipe culverts or concrete bridges and thus forever do away with the further expense of the maintenance of expensive and dangerous wooden structures." Within a few years, readily constructed standardized bridges of concrete were being built throughout the state.

In 1930, the roadway width for all standard plan bridges was increased to 27 feet in order to accommodate the increasing demands of automobile and truck traffic (State Roads Commission 1930). The range of span lengths remained the same, but there were some changes designed to increase the load bearing capacities. The reinforcing bars increased in thickness. Visually, the 1930 design can be distinguished from its predecessors by the pierced concrete railing that was introduced at this time.

In 1933, a new set of standard plans were introduced by the State Roads Commission. This time their preparation was not announced in the Report; new standard plans were by this time nothing special - they had indeed become standard. Once again accommodating the ever-increasing demands of traffic, the roadway was increased, this time to 30 feet. The slab span's reinforcing bars remained the same diameter but were placed closer together to achieve still more load capacity.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

The bridge is located in an area which does not appear to be eligible for historic designation.

Is the bridge a significant example of its type?

The bridge is a good example of the State Roads Commission standard bridge plans of the 1930s, which possesses a high degree of integrity.

Does the bridge retain integrity of important elements described in Context Addendum?

The bridge retains the character-defining elements of its type, as defined by the Statewide Historic Bridge Context, including longitudinal beams, slab, integral parapets, abutments and wing walls.

Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

This bridge is a significant example of the work of the State Roads Commission in the 1930s.

Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.

т	110	T T 🗸)GR	 	W 7.
ж			11 <i>–</i> K	-	
1.3			, 011	 	

County inspection/bridge files	SHA inspection/bridge files	X
Other (list):		

Ketchum, Milo S.

- 1908 The Design of Highway Bridges and the Calculation of Stresses in Bridge Trusses. The Engineering News Publishing Co., New York.
- 1920 The Design of Highway Bridges of Steel, Timber and Concrete. Second edition. McGraw-Hill Book Company, New York.

Lay, Maxwell Gordon

1992 Ways of the World: A History of the World's Roads and of the Vehicles That Used Them. Rutgers University Press, New Brunswick, New Jersey.

Luten, Daniel B.

- 1912 Concrete Bridges. American Concrete Institute Proceedings 8:631-640.
- 1917 Reinforced Concrete Bridges. National Bridge Company, Indianapolis, Indiana.

Maryland State Roads Commission

- 1930a Report of the State Roads Commission for the Years 1927, 1928, 1929 and 1930. State of Maryland, State Roads Commission, Baltimore.
- 1930b Standard Plans. State of Maryland, State Roads Commission, Baltimore.

Taylor, Frederick W., Sanford E. Thompson, and Edward Smulski


1939 Reinforced-Concrete Bridges with Formulas Applicable to Structural Steel and Concrete. John Wiley & Sons, Inc., New York.

Tyrrell, H. Grattan

1909 Concrete Bridges and Culverts for Both Railroads and Highways. The Myron C. Clark Publishing Company, Chicago and New York.

SURVEYOR:

Date bridge recorde	ed <u>2/25/97</u>	***
Name of surveyor _	Caroline Hall	
Organization/Addre	ess P.A.C. Spero & O	Co., 40 W. Chesapeake Avenue, Baltimore, MD 21204
Phone number (410)	296-1685	FAX number (410) 296-1670





1. HA -1977 2. MD 136 over Big Branch (12.030) 3. Harford Co, MD 4 Caroline Hall 5 3/97 6 MD SHPO 7 south side 8.10/5



1. HA-1977 2. MD 136 over Big Branch (12030) 3 Harfard Com 4 Caroline Hall 5. 3/97 6 MD SHPO 7. roadway approach 8.2015



1, HA-1977 2. MD 136 over Big Branch (12030) 3. Harford a, mo 4. Caroline Hall 5.3/97 6. MD SHPO 7. roadway approach

8.3845



1. HA-1977 2. MD 136 over Big Branch (12030) 3. Harford Co, MO. 4. Caroline Hall 5.3/97 6. MD SHPO 7. north paraget 8.4015



1. HA = 1977 2. MD 136 0 10 Bug Branch (12030) 3. Harford 6, MD 4. Caroline Hall 5 3/97 6 MDSHPD 7, south parapet 8.5015


930160

INDIVIDUAL PROPERTY/DISTRICT MARYLAND HISTORICAL TRUST INTERNAL NR-ELIGIBILITY REVIEW FORM

Property/District Name: <u>Bridge #12030</u>	Survey Number: HA — 1977
Project: MD 136 over Big Branch, Harford County	Agency: SHA (state funded)
Site visit by MHT Staff: X no yes Name	Date
Eligibility recommended X Eligibility no	ot recommended
Criteria:AB _X_CD Considerations:	ABCDEFGNone
Justification for decision: (Use continuation she	et if necessary and attach map)
Based on the available information, we believe Bridge under Criterion C. The concrete girder bridge whirmula embodies distinctive characteristics of seesses design features, including a pierced rail which create a distinctive whole. The bridge appear of historic character.	ch was constructed in 1934 to a standard type and period. Although simple, in ing and scored wing walls and abutments,
Double-to-tion on the constant to the constant	
Documentation on the property/district is presented	in: Project File
Preparedby:_RitaSuffness	
Elizabeth Hannold Reviewer, Office of Preservation Services	July 7, 1993 Date
NR program soncurrence: yes no not	applicable
R landreus	# 7. 8-93
Reviewer, NR program	Date Only

Survey No. HA HA-1977

MARYLAND COMPREHENSIVE	HISTORIC	PRESERVATION	PLAN	DATA	- HISTORIC	(
Geographic Region:						
Eastern Shore	(all	Eastern Sho		nties,	and Cecil)
Western Shore	(Anne	•	Calvert,	Char	•	
	Prin	•		St. Mar		
Piedmont	(Balt				Carroll, Montgomery)	
		derick, Harfo		loward, Washii		
Western Maryland	(Alle	gany, Garret	t and	Wasiiii	ngturi	
Chronological/Developmental	Periods:	1				
Paleo-Indian		10000-7500	B.C.			
Early Archaic		7500-6000	B.C.			
Middle Archaic		6000-4000	B.C.			
Late Archaic		4000-2000	B.C.			
Early Woodland			B.C.			
Middle Woodland			- A.D.	900		
Late Woodland/Archaic		A.D. 900-16				
Contact and Settlement		A.D. 1570-1				
Rural Agrarian Intensificati	on	A.D. 1680-1				
Agricultural-Industrial	ransition	A.D. 1815-1				
Industrial/Urban Dominance		A.D. 1870-1				
Modern Period		A.D. 1930-F				
Unknown Period (pre	historic	histori	c)			
Prehistoric Period Themes:		IV. Hist	oric	Period	Themes:	
Subsistence		Agriculture				
Settlement	x_		•	andscape	Architect	ur
		and Communi		lanning		
Political		Economic	(Commerc	ial	and Industr	aı
Demographic		_ Government/L	aW			
Religion		_ Military				
Technology		_ Religion		امستماد		
Environmental Adaption		Social/Educa		itturat		
		_ Transportati	on			
esource Type:						
Category: <u>Structure</u>						
Historic Environment: _	Rural					
Historic Function(s) and	Use(s):	Transportation	<u> </u>			
						
Known Design Source:	Jnknown					





Bridge No. 12030 Dat	te 5/10/93
MD RTE 136 over BIG BI	RANCH
Other (Describe) NORTH F	PARAPET,
EAST	
•	HA-1977
•	
•	
•	
•	



Bridge No. 12030	Date 5/10/93
MDRTE 136 over BK	/
Other (Describe) NOR	TH PARAPET,
WEST SIDE	
•	HA-197
•	
•	
•	
•	



Bridge	No. 17030	Date 5/10/93	_
MDR	TE.136_over_E	BIG BRANCH	_
Other	(Describe)	DERSIDE OF DECK	2
SCUT	<u>H</u>		
•	making aranimatahan	HA-19-	77
•			
•			_
•			_



Bridge No. 12030	e 5/10/93	
MD RTE. 136 0	RANCH	
Other (Descri)	SIDE OF DECK,	
NORTH SU		
CLOOK	HA-1977	
0		
0		



Bridge	No. 17030	_Date_5	10/9	3
	E 136 over BiG			
Other	(Describe) /	· · · <u>V</u>	VING	WALL
•			HA.	-1977
•				
•				
•				
•				
•				

News A

ALDON)